



ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø12

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production



X = Rpm vite
 X = Screw rpm
 X = Schnecke U.p.m.
 X = T/min de la vis



Y = kg/h
 Y = kg/h
 Y = kg/h
 Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

GP12-05

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø14

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production





X = Rpm vite
 X = Screw rpm
 X = Schnecke U.p.m.
 X = T/min de la vis

Y = kg/h
 Y = kg/h
 Y = kg/h
 Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø18

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production





X = Rpm vite Y = kg/h
 X = Screw rpm Y = kg/h
 X = Schnecke U.p.m. Y = kg/h
 X = T/min de la vis Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

GP18-03

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø25

Esempi di produzione
Examples of production
Produktion Beispiele
Exemples de production



X = Rpm vite
X = Screw rpm
X = Schnecke U.p.m.
X = T/min de la vis



Y = kg/h
Y = kg/h
Y = kg/h
Y = kg/h

I dati non sono impegnativi
Non binding data
Die Daten sind nicht verbindlich
Les données nous n'engagent pas

GP25-01

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø30

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production



X = Rpm vite
 X = Screw rpm
 X = Schnecke U.p.m.
 X = T/min de la vis



Y = kg/h
 Y = kg/h
 Y = kg/h
 Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

GP30-02

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø35

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production



X = Rpm vite
 X = Screw rpm
 X = Schnecke U.p.m.
 X = T/min de la vis



Y = kg/h
 Y = kg/h
 Y = kg/h
 Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

GP35-02

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø45

Esempi di produzione
 Examples of production
 Produktion Beispiele
 Exemples de production





X = Rpm vite Y = kg/h
 X = Screw rpm Y = kg/h
 X = Schnecke U.p.m. Y = kg/h
 X = T/min de la vis Y = kg/h

I dati non sono impegnativi
 Non binding data
 Die Daten sind nicht verbindlich
 Les données nous n'engagent pas

GP45-02

ESTRUSORE-EXTRUDER-EXTRUDEUSE Ø60

Esempi di produzione
Examples of production
Produktion Beispiele
Exemples de production



X = Rpm vite
X = Screw rpm
X = Schnecke U.p.m.
X = T/min de la vis

Y = kg/h
Y = kg/h
Y = kg/h
Y = kg/h

I dati non sono impegnativi
Non binding data
Die Daten sind nicht verbindlich
Les données nous n'engagent pas

GP60-01